


# E.P.G.C Plot 3HS



Contains Ordnance Survey data © Crown copyright and database right 2018

## Surface Water Flooding





Rainhill Hospital Playing Fields, Late 80s  
Grid Reference = SJ 49153 91385

SHGBA. Image No 3.



Flooded Infront of and beyond In Front Of Residents The Large Lake, EPGC, 11th January 2021 @ 11.06  
Grid Reference SJ 49153 91385

SHGBA Image No 4.





Packhorse Type Bridge For Golfers Near 15th Hole, The Flood Measured 1.2m Above Normal Level.

Grid Reference No = SJ 49153 91385

SHGBA Image No 5.



Top of Bridge Walls Near 15th Hole, 1.1m to Usual Level, 21st January 2021 @ 11.15am  
Grid Reference = SJ 49153 91385

SHGBA, Image No 6.





Floods Well Outside Of Large Lakes Safety Fencing. 21st January 2001 @ 12.35pm

Grid Reference, SJ 49153 91385 SHGBA

SHGBA Image No 7.






East Side Of 18 th Hole, Behind ClubHouse, 21st January 2001 @ 13.15pm  
Grid Reference No SJ 49153 91385 SHGBA Image No 8.



West of 18th Hole & Near Teeing Off Point. Top HS Is "Ryder Court" Which Has Been Flooded  
In The Past.  
Grid Reference No = SJ 49153 91385 SHGBA Image No 9.





Flood Fairway & Bunker In Front Of Ryder Court Gagens.  
Grid Referenc, SJ 49153 91385

SHGBA Image No 10.



Brook Overflowed Into Neighbouring Field, 22nd January 2001 @ 9.30am.  
Grid Reference No SJ 49153 91385 SHGBA

SHGBA Image No 11.





**It's Flooding Even More 22nd January 2021 @ 10.30am**  
**Grid Reference SJ 49153 91385**

**SHGBA Image No 12.**









EPGC Main & Only Entrance Fully Flooded 21st January 2021 @ 11.47am  
Grid Reference No SJ 49153 91385 SHGBA Image No 15.